BMW G12 750Li Sedan / Repair Manuals and Technical Data / 61 General vehicle electrical system / 61 31 Switch, sensor /

61 31 321 Removing and installing radio and A/C control panel



Careless handling of tools and sharp-edged components. Scratch, surface damage.


- Protect working area.
- Handle tools and components carefully.

PRELIMINARY WORK


1 – Removing the front storage compartment

Prerequisite

The cover of the storage compartment is open.



- If applicable, remove the insert (1).
- Remove the insert mat (2).
- Lift the latch mechanisms (3) and push the storage compartment towards the front.




- Place the storage compartment in an upright position.
- Disconnect the connector for the USB port (1).
- Unlock and disconnect all connectors (arrows) on the bottom of the storage compartment.
- · Remove the storage compartment.

2 - Remove the finisher on the right instrument panel




- Unclip the side panel (1) at the side using the special tool <u>0 496 569 (00 9 325)</u>.
- Disconnect the plug connection and remove the side panel (1).
- Loosen screws (2).



- Lever out the decorative strip (1) from clamps (2).
- Disconnect the plug connections and remove the decorative strip (1).

MAIN WORK

3 - Removing the radio operating unit and the air conditioning control panel




► Remove the centre stack trim

Unclip the centre stack trim (1) with the special tool
 0 496 569 (00 9 325) toward the bottom.




• If installed:

Loosen both screws (1) on the bottom.




- Unlock the clamps (1) on the left and right and simultaneously press with special tool <u>2 298 505</u>.
- Remove the radio operating unit and the air conditioning control panel (2).




- Unlock plug connection (1) and disconnect.
- Feed out cable (arrows) of the radio operating unit and of the air conditioning control panel (2).
- Make sure the connector (3) is **not** disconnected.


4 – Installing radio operating unit and air conditioning control panel



- Connect the connector (1) with the radio operating unit and the air conditioning control panel (2).
- Insert the cable (arrows).




• Clip the radio control unit and air conditioning controls (1) into the instrument panel trim.



• If installed:

Tighten both screws (1) on the bottom.

▶ Install the centre stack trim






Latch mechanisms, guides and mounting elements must not be damaged or missing.

- Check the latch mechanisms and guides on the trim
 (1) of the centre stack.
- Clip in the trim (1) of the centre stack upwards.

POSTPROCESSES

5 - Install the finisher on the right instrument panel



- Position decorative strip (1) and connect all the connectors.
- Engage decorative strip (1) in all clamps (2).



• Tighten down screws (2).


Instrument panel

Screw


Tightening 1,8 Nm torque

• Connect the connector and mount side panel (1).

6 - Installing the front storage compartment



- Align the storage compartment with the centre console when it is in upright position.
- Connect the connector for the USB port (1).
- Connect all connectors on the bottom of the storage compartment.



- Insert the storage compartment (1) into the centre console.
- Forcefully pull the storage compartment (1) backwards and engage it.
- Insert the insert mat.
- If applicable insert the insert (2).

Additional Information

Overview of Tightening Torques

Instrument panel Used in step 5

Screw Tightening torque 1,8 Nm


Overview of Special Tools

0 496 569 (00 9 325) Wedge



Common		Used in step	2	3
Usage	(Panel wedge) From special tool replaces 317 (different materia	panel wedge	00	9
Included in the tool or work	0 490 527			
Storage location	Individual			
Replaced by				
In connection with				
SI-Number	41 01 09 (507)			

2 298 505 Wedge



Common		Used in step	3
Usage	Set (delivery of 2 pieces)	
Included in the tool or work			
Storage location	C34		
Replaced by			
In connection with			
SI-Number	01 03 12 (792)		

For informational purposes only. The information on this website is provided AS-IS with no warranties, express or implied, and is not guaranteed to be error-free, up-to-date or complete. NewTIS and BMW assume no liability for any loss or damage arising from the use or reliance on the information and content on this website. The content on this website is subject to change without notice.